

AirMate

Phone conversation outside the broadcast.

Fixed settings:

- Set all Aux-pots on modules via jumpers pre-fader (position 3-4).
- Turn module aux-pot of Announcer and Telco clockwise until 2 o'clock.
- Turn master Aux-Send clockwise until 2 o'clock.
- Connect recorder to Aux output.
- Push Talk Back to Clean Feed.

When recording conversation during broadcast:

- Announcer/DJ fader closed, module "ON" (Led lights).
- Telco fader (normally module 8) closed, module "ON" (Led lights).
- Turn on Aux Send CUE (now the technician hears what's being recorded)
- Turn on Ann. Follow Phones (now the Announcer/DJ hears what's being recorded)
- Turn down the Clean-Feed potentiometer (now the caller does not hear the Broadcast anymore)
- During conversation push the Talk-Back so the caller hears the Announcer/DJ.

Alternative solution with better DJ signal to the caller (without using the internal TB mic):

Use the Aux return as external Clean-Feed input:

- On the back connector panel use a Y cable to connect Aux Send with Aux Return and recorder.
- On PCB AirMate-3, remove R4 and R5 (Aux-return is disconnected from the master).
- Make a new connection between resistors 10k from pcb AirMate-3 R4/R5 to pcb AirMate-4 IC1-pin2 (output driver clean feed)
- In this way the announcer/DJ MIC signal goes directly to the caller, instead of the internal electret mic signal.

Both solutions always bring the original DJ's MIC signal into the recording!

AirMate

Telefoon gesprek opnemen buiten de uitzending om.

Vaste instelling:

- Alle Aux-pots op de modules via jumpers pre-fader zetten (position 3-4).
- Module aux-pot van Announcer en Telco module openen.
- De Aux-Send pot openzetten.
- Aux output aansluiten op recorder.
- Talk Back to Clean Feed aan zetten

Moment van opname buiten de uitzending om:

- Announcer fader dicht, module "ON" (Led licht op).
- Telco fader dicht module op "ON" (Led licht op).
- Aux Send CUE aan zetten (nu hoort de techneut wat er gaat opgenomen worden)
- Ann. Follow Phones aanzetten (nu hoort de Announcer wat er gaat opgenomen worden)
- Clean-Feed pot dicht draaien (nu hoort de Telco de uitzending niet meer)
- Tijdens gesprek TalkBack in drukken zodat Telco de Ann. hoort.

Alternatieve oplossing voor een beter DJ signaal alleen naar de beller:

Modificatie kan zijn Aux return gebruiken voor externe CleanFeed ingang:

- Achter zijde Aux Send doorkoppelen met Aux Return via split kabel (de recorder moet ook aangesloten blijven)
- Op AirMate-3, R4 en R5 verwijderen (Aux-return gaan nu niet meer naar master).
- Verbinding maken via 10k weerstand uit AirMate-3 R4/R5 naar AirMate-4 IC1-pin2 (cleanfeed uitgang).
- In deze situatie gaat het Mic announcer/DJ signaal direct naar de beller, in plaats van het interne electret signaal.

Beide oplossingen brengen het originele DJ MIC signaal op de opnames!